LUFTFARTSVERKET
Hovedadministrasjonen
Luftfartsinspeksjonen
Postboks 8124 Dep., 0032 Oslo
Telefon : 22 94 20 00
Telefax : 22 94 23 91
Tigr. : CIVILAIR
Telex : 71032 enfb n

LUFTDYKTIGHETSPÅBUD (LDP)

TILBEHØR MICHELIN - 1

Med hjemmel om lov om luftfart av 11. juni 1993 kap. IV § 4-1 og kap. XV § 15-4, fastsetter Luftfartsverket følgende forskrift om luftdyktighet.

96-007 KONTROLL AV DEKK

Påbudet gjelder:

Michelin Aircraft Tire Corporation dekk med del nr. (P/N) 028-520-1 (22x5.75-12/10PR), som har serienummer som listet i vedlagte kopi av FAA AD 95-24-10.

Påbudet omfatter:

Utfør tiltak som beskrevet i vedlagte kopi av FAA AD 95-24-10.

Tid for utførelse:

Til de tider og intervaller som beskrevet i vedlagte kopi av FAA AD 95-24-10, med virkning fra denne LDP's gyldighetsdato.

Referanse:

FAA AD 95-24-10.

Gyldighetsdato:

01.01.95.

BW 95-24

MICHELIN AIRCRAFT TIRE CORP. AIRWORTHINESS DIRECTIVE PRIORITY LETTER APPLIANCE LARGE AIRCRAFT

95-24-10 MICHELIN AIRCRAFT TIRE CORPORATION: Priority Letter issued on November 21, 1995. Docket No. 95-CE-88-AD.

Applicability: Part number (P/N) 028-520-1 (22x5.75-12/10PR) tires with the following serial numbers that are installed on the main landing gear of, but not limited to, Cessna Model 650 (Citation III, VI, and VII) airplanes that are certificated in any category:

| Serial Nos. | Serial Nos. | Serial Nos. | Serial Nos. |
|-------------|-------------|-------------|-------------|
| 4279N00339 | 4279N00340 | 4279N00341 | 4279N00342 |
| 4279N00343 | 4279N00597 | 4279N00598 | 4279N00599 |
| 4279N00600 | 4279N00601 | 4280N00075 | 4280N00199 |
| 4280N00200 | 4280N00201 | 4280N00203 | 4280N00204 |
| 4280N00205 | 4280N00206 | 4280N00360 | 4280N00361 |
| 4282N00352 | 4283N00099 | 4283N00100 | 4283N00101 |
| 4283N00102 | 4283N00200 | 4283N00201 | 4283N00202 |
| 4283N00453 | 4283N00454 | 4283N00455 | 4283N00456 |
| 4284N00612 | 4284N00613 | 4284N00614 | 4284N00615 |
| 4284N00616 | 4285N00100 | 4285N00101 | 4285N00102 |
| 4285N00103 | 4285N00104 | 4285N00105 | 4285N00106 |
| 4285N00107 | 4285N00108 | 4285N00347 | 4285N00348 |
| 4285N00349 | 4285N00353 | 4285N00354 | 4285N00355 |
| 4285N00356 | 4285N00608 | 4285N00609 | 4286N00103 |
| 4286N00104 | 4286N00105 | 4286N00106 | 4286N00442 |
| 4286N00443 | 4286N00444 | 4286N00445 | 4286N00446 |
| 4286N00447 | 4286N00448 | 4286N00449 | 4286N00450 |
| 4286N00600 | 4286N00601 | 4286N00602 | 4286N00603 |
| 4286N00604 | 4286N00605 | 4286N00606 | 4286N00608 |
| 4286N00609 | 4287N00088 | 4287N00089 | 4287N00090 |
| 4287N00091 | 4287N00092 | 4287N00093 | 4287N00094 |
| 4287N00095 | 4287N00096 | 4287N00097 | 4287N00357 |
| 4287N00358 | 4287N00359 | 4287N00360 | 4287N00361 |
| 4287N00362 | 4287N00363 | 4287N00364 | 4288N00118 |
| 4288N00119 | 4288N00120 | 4288N00121 | 4288N00302 |
| 4288N00303 | 4288N00304 | 4288N00305 | 4288N00306 |
| 4288N00307 | 4290N00111 | 4290N00113 | 4290N00114 |
| 4290N00115 | 4290N00116 | 4290N00117 | 4290N00355 |
| 4290N00356 | 4290N00606 | 4290N00607 | 4290N00608 |
| 4290N00609 | 4290N00610 | 4290N00611 | 4290N00612 |
| 4291N00082 | 4291N00083 | 4291N00084 | 4291N00085 |
| 4291N00086 | 4291N00087 | 4291N00088 | 4291N00089 |
| 4291N00091 | 4291N00273 | 4291N00274 | 4291N00275 |
| 4291N00276 | 4291N00277 | 4291N00278 | 4291N00620 |
| 4291N00621 | | | |

NOTE 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required prior to further flight after receipt of this AD and thereafter upon stallation of one of the affected tires, unless already accomplished.

To prevent loss of control of the airplane during landing operations because of P/N 028-520-1 (22x5.75-12/10PR) tire failure, accomplish the following:

- (a) Replace any of the affected P/N 028-520-1 (22x5.75-12/10PR) tires with an FAA-approved tire.
- (b) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.
- (c) An alternative method of compliance or adjustment of the compliance time that provides an equivalent level of safety may be approved by the Manager, Atlanta Aircraft Certification Office (ACO), Campus Building, 1701 Columbia Avenue, suite 2-160, College Park, Georgia 30337-2748. The request shall be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Atlanta ACO.

NOTE 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Atlanta ACO.

- (d) Copies of the applicable service information may be obtained from Michelin Aircraft Tire Corporation, 9700 Research Drive, Charlotte, North Carolina. This information may also be examined at the FAA, Central Region, Office of the Assistant Chief Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.
- (e) Priority Letter AD 95-24-10, issued November 21, 1995, becomes effective immediately _pon receipt.

FOR FURTHER INFORMATION CONTACT: Ms. Denise Bosonetto, Aerospace Engineer, FAA, Atlanta Aircraft Certification Office, Campus Building, 1701 Columbia Avenue, suite 2-160, College Park, Georgia 30337-2748; telephone (404) 305-7379; facsimile (404) 305-7348.

BLANK